


SALES UPDATE December 2004



Product Application Update

This information relays changes related to product design or enhancements, and informs you of installation or fitment issues that are being resolved. These changes are occurring as an Engineering Change Order (ECO) "running change" to existing part numbers, and are typically a result of changes in the vehicle's design or trim packages. To inform Westin of fitment or installation issues, please contact Emilio Gomez, our Product Coordinator & Technical Support Rep via email at sales/marketing@westinautomotive.com, or by phone at (800) 345-8476 ext. 457.

Please make the changes listed below in your 2005 Catalog/Jobber/WD.

The Bed Extender mounting brackets have been redesigned to accommodate the new Quick Release Bracket system. The mounting hardware has been replaced with new quick release brackets and "L" brackets. Update all literature with the new numbers and new pricing.

| OLD PART # | CURRENT DESCRIPTION | SUPERCEDED BY PART # |
|------------|---|----------------------|
| 10-9901 | Replacement Mounting Hardware for #10-0000 & #10-0020 | 10-9903 |
| 10-9902 | Replacement Mounting Hardware for #10-0010 | 10-9904 |

For more information contact: **Emilio Gomez**
Tel: 800-345-8476 x 457 Fax: 626-251-1032
Email: egomez@westinautomotive.com