


sales update

SALES UPDATE January 2005



2005 Product Application Update

This information relays changes related to product design or enhancements, and informs you of installation or fitment issues that are being resolved. These changes are occurring as an Engineering Change Order (ECO) "running change" to existing part numbers, and are typically a result of changes in the vehicle's design or trim packages. To inform Westin of fitment or installation issues, please contact Emilio Gomez, our Product Coordinator & Technical Support Rep via email at sales/marketing@westinautomotive.com, or by phone at (800) 345-8476 ext. 457.

CATALOG CORRECTION

ECO	Application Correction:	Westin Action Taken:
N/A	<p>Application Update - 99-04 BMW X5 w/factory rack</p> <p>Incorrect: Currently listed 15-4015 45"</p> <p>Correct: 15-4025 50"</p>	<p>The Sport Series Cross Bar for the BMW X5 has been changed from 45" in length to 50" length. The changes will only reflect the Sport series, the HD/Outback series will not need to be corrected.</p> <p>Please make corrections on page 45 of your 2005 Westin Catalog.</p>

CATALOG UPDATE

Application Correction:	Westin Action Taken:
<p>Tail Light Guard Updates</p> <p>Page #63 of the 2005 Westin Catalog</p>	<p>The footnotes have been omitted in the 2005 catalog. Please make the following corrections/updates on your catalog.</p> <p>Footnote:</p> <ul style="list-style-type: none"> * Requires minor drilling 1. Includes C/K models sold in 1999. 2. Does not include stepside, flareside or 2001-03 Supercrews. 3. Does not fit models with dual rear doors. 4. Excludes 2002 models sold in 2001.

For more information contact: **Emilio Gomez**
 Tel: 800-345-8476 x 457 Fax: 626-251-1032
 Email: egomez@westinautomotive.com

sales update

SALES UPDATE

January 2005

WEBSITE CORRECTION

Application Correction:

Ladder Slide Kit
Part No. - 18-9135

Contents:

- 4 Ladder Slides
- 2 Load Holders
- 1 Camloc Ladder strap
- 2 Ladder Hoops

Westin Action Taken:

Please note that the following updates have been corrected on the our website. Previously the website stated that Part No. 18-9135 (Ladder Slide kit) included 2 camloc ladder straps, this accessory application is correct in the 2005 Westin catalog but was incorrect on our website. The website has been corrected as of 1-24-05.

www.westinautomotive.com

JOBBER ADDENDUM

FATBOY Classic Grille Guard

PART NUMBER	DESCRIPTION & APPLICATION	FINISH	POP CLASS	UPC CODE	L	W	H	WT	UPS RPS	SPECIAL ORDER FRT CODE	JOBBER PRICE	RETAIL PRICE
35-5020	DODGE Ram 1500 02-05 (2500/3500 03-05)	Chrome	New	707742006153	84	23	9	100	N	G5	\$528.75	\$705.00
35-5050	FORD F250/350HD Superduty 99-04	Chrome	New	707742006412	84	23	9	100	N	G5	\$468.62	\$624.83
35-5080	FORD F150 (excl. Heritage Edition) 04-05	Chrome	New	707742006467	80	23	9	100	N	G5	\$468.62	\$624.83

For more information contact: **Emilio Gomez**
 Tel: 800-345-8476 x 457 Fax: 626-251-1032
 Email: egomez@westinautomotive.com