


sales update

SALES UPDATE

February 2005



2005 Product Application Update

This information relays changes related to product design or enhancements, and informs you of installation or fitment issues that are being resolved. These changes are occurring as an Engineering Change Order (ECO) "running change" to existing part numbers, and are typically a result of changes in the vehicle's design or trim packages. To inform Westin of fitment or installation issues, please contact Emilio Gomez, our Product Coordinator & Technical Support Rep via email at sales/marketing@westinautomotive.com, or by phone at (800) 345-8476 ext. 457.

APPLICATION UPDATE

Application Correction:

Sportsman Grille Guard Section:
Footnotes on page #13

Additional Footnote #17 applies
to the Dodge Ram applications.
2002-05 Dodge Ram 1500¹⁷
2003-05 Dodge Ram 2500/3500¹⁷

Part No's:

40-1205 41-1205 44-1200

Westin Action Taken:

REPLACES FOOTNOTES ON PG. 13

- 1 See separate listings for 1999-04, Silverado and Sierra body styles.
- 2 Excludes Sport Models with a diesel engine.
- 3 On models without tow hooks, some modification of lower bumper fascia is necessary.
- 4 Must have tow hooks.
- 5 Cutting of air dam is necessary to complete installation.
- 6 Bumper cover must be removed to install the mount brackets. Replacement fastener are provided to re-attach cover.
- 7 Vehicle's grille must be removed to install the mount brackets. Easy to remove and snaps back into place.
- 8 Excludes 1500 Sport models 99-01, 2500/3500 Sport models 99-02.
- 9 Excludes 2000-03 Off Road Edition with tow hooks.
- 10 Excludes new 2003 models sold in 2002.
- 11 Does not fit GMC Sierra.
- 12 On 1998 models, enlarging the vehicle's frame hole is required using 1/2" drill bit.
- 13 Access to the tow hooks is limited after installation.
- 14 Existing underbody shields must be removed or modified to install.
- 15 Minor trimming of air dam may be required.
- 16 Excludes Renegade Edition.
- 17 Tow hooks must be removed, if equipped.

For more information contact: **Emilio Gomez**
 Tel: 800-345-8476 x 457 Fax: 626-251-1032
 Email: egomez@westinautomotive.com