


# SALES UPDATE

## AUGUST 2005



### 2005 Product Application Update

This information relays changes related to product design or enhancements, and informs you of installation or fitment issues that are being resolved. These changes are occurring as an Engineering Change Order (ECO) "running change" to existing part numbers, and are typically a result of changes in the vehicle's design or trim packages. To inform Westin of fitment or installation issues, please contact Technical Support Rep via email at [tech1@westinautomotive.com](mailto:tech1@westinautomotive.com), or by phone at (800) 793-7846.

### 2006 Chevy Silverado / GMC Sierra Step Up Products

Westin has confirmed that the 2006 Chevy/GMC Silverado/Sierra trucks have had a body mount change that affects the fit of the step products listed below. The factory body mount bolts used to attach the truck cab to the frame have changed. The bolt diameter is larger and longer but will adapt through the top slots/holes provided on our mount brackets. The replacement hardware body mount bolts supplied by Westin are **NOT NEEDED** on the 2006 models.

#### AFFECTED APPLICATIONS

##### 3" Round Step Bars

###### REGULAR CAB:

###### Signature Series

- 25-1400 (chrome)
- 25-1405 (black)

###### Platinum Series

- 26-1400 (CPS)
- 26-1405 (BPS)

###### EXT. CAB:

###### Signature Series

- 25-1680 (chrome)
- 25-1685 (black)

###### Polished Stainless

- 23-1680 (Polished)

###### Platinum Series

- 26-1680 (CPS)
- 26-1685 (BPS)

###### CREW CAB:

###### Signature Series

- 25-1950 (chrome)
- 25-1955 (black)

###### Polished Stainless

- 23-1950 (chrome)

###### Platinum Series

- 26-1950 (CPS)
- 26-1955 (BPS)

##### Oval Tube Step

###### REGULAR/EXT. CAB: LD Models

- 22-1085 (mount kit)

###### REGULAR/EXT. CAB: HD Models

- 22-1065 (mount kit)

###### CREW CAB

- 22-1075 (mount kit)

##### Step Boards

- Not Affected

##### Sport Tubes

- Not Affected

##### W2W Step Bars

###### EXT. CAB:

- 24-4030 (CPS)
- 24-4035 (BPS)

###### CREW CAB:

- 24-4000 (CPS)
- 24-4005 (BPS)

###### 1500 CREW CAB:

- 24-4150 (CPS)
- 24-4155 (BPS)

#### CORRECTIVE ACTION

- Existing instruction sheets will be updated and re-distributed via News Broadcast.
- Instruction sheets found on the Westin website will be updated as soon as files are available.
- A note will be posted for the affected applications on the respective web pages.

For more information contact: Technical Support

Tel: 1-800-793-7846

Email: [tech1@westinautomotive.com](mailto:tech1@westinautomotive.com)