INSTALLATION INSTRUCTIONS HDX DROP W2W NEFF STEP BARS



APPLICATION:

2020 Chevrolet/GMC Silverado/Sierra 2500/3500 Crew Cab 6.5' and 8'

bed

PART NUMBER: 56-534775, 56-5347752, 56-534765, 56-5347652

ITEM	QUANTITY	DESCRIPTION	TOOLS NEEDED
1	2	STEP BAR ASSEMBLY DRIVER AND PASSENGER	RATCHET
2,3	2	CENTER MOUNT BRACKET, DRIVER (2) AND PASSENGER (3)	TORQUE WRENCH
4	4	MOUNTING BRACKET	SOCKET EXT.
5	18	M8 HEX HEAD BOLT LONG (YELLOW ZINC)	13MM SOCKET
6	12	M8 HEX HEAD BOLT SHORT (YELLOW ZINC)	13MM WRENCH
7	32	M8 FLAT WASHER (YELLOW ZINC)	18MM SOCKET
8	32	M8 LOCK WASHER (YELLOW ZINC)	18MM WRENCH
9	2	M12 ISOLATOR KIT	
10, 11	2	TOP ISOLATOR BRACKET, DRIVER (10) AND PASSENGER (11)	
12, 13	2	BOTTOM ISOLATOR BRACKET, DRIVER (12) AND PASSENGER (13)	
14	4	ISOLATOR KIT	
15	2	M8 HEX NUT	

Driver Side Shown
8 ft. Bed Shown

ITEM 1

ITEM 10

ITEM 12

ITEM 2


ITEM 3

ITEM 4

PROCEDURE

1. Remove contents from box, verify if all parts listed are present and free from damage. Carefully read and understand all instructions before attempting installation.

Failure to identify damage before installation could lead to a rejection of any claim.





Note Asymmetric

1


- 2. Starting on the driver side, remove the rubber plugs located on the rocker panel at each mounting location. See **Figure 1**.
- 3. **For models with threaded holes:** At each bracket mounting location on the rocker panel there should be a welded factory nut.









- 4. Locate (1) Center Mount Bracket (Item 2-3). Loosely secure Center Mount Bracket to the rocker panel using (2) M8 hex head bolt long, (2) M8 flat washer, and (2) M8 lock washer. See **Figure 3.** Refer to **Page 4** bracket orientation figures.
- 5. Attach the Bottom Isolator Bracket (12) to the Top Isolator Bracket (10) using the Isolator Kit (9) hardware. See **Figure 4.**






- 6. Under the front of the bed, there is two factory bolts as shown in **Figure 5.** Remove these bolts.
- 7. Using Preexisting factory bolts, mount the isolator bracket assembly (10) in between the bed and factory bed bracket. **See Figures 5-7**





bed.



- For Step Board installation, tilt board at an angle to insert brackets into mounting locations. With the previously installed mounting brackets use the supplied M8 hardware with the short M8 hex head bolt, then loosely install. See Figures 8 & 9.
- Align and adjust the step bars and brackets as needed, then fully tighten all hardware: M8 to 15-18 ft-lbs.










Care Instructions

- REGULAR WAXING IS RECOMMENDED. DO NOT USE ANY TYPE OF POLISH OR WAX THAT MAY CONTAIN ABRASIVES.
- STAINLESS STEEL PRODUCTS CAN BE CLEANED WITH MILD SOAP AND WATER. STAINLESS STEEL POLISH SHOULD BE USED TO POLISH SMALL SCRATCHES.
- GLOSS BLACK FINISHES SHOULD BE CLEANED WITH MILD SOAP AND WATER.







WARNING



Failure to follow these instructions could lead to death, personal injury, and / or property damage.

Failure to follow these instructions could lead to death, personal injury, and / or property damage.

FASTENERS:

All Westin supplied fasteners must be utilized and installed in accordance with the installation instructions and apply torque to the specifications as defined. DOUBLE CHECK ALL FASTENERS BEFORE INITIAL USE, AND PERIODICALLY IN THE FUTURE TO ENSURE PROPER FUNCTION AND SAFETY.

DRILLING:

Most Westin products do not require drilling for installation. If drilling is defined as required, use caution when drilling a vehicle. FAILURE TO REVIEW AN AREA TO BE DRILLED MAY RESULT IN PERSONAL INJURY AND/OR INJURY TO OTHERS AS WELL AS VEHICLE DAMAGE.

EYE PROTECTION:

ALWAYS WEAR SAFETY GLASSES OR GOGGLES DURING THE INSTALLATION PROCESS TO AVOID PERSONAL INJURY.

MAXIMUM TOWING/CARRYING CAPACITY: (if applicable)

The Westin Receiver Hitches will have a visible tow rating label affixed directly on the product. User should never exceed the vehicle manufacturers maximum tow and weight rating regardless of the capacity of the hitch. FAILURE TO FOLLOW THESE GUIDELINES WILL VOID THE WESTIN WARRANTY AND MAY RESULT IN PERSONAL INJURY AND/OR INJURY TO OTHERS AS WELL AS VEHICLE DAMAGE.

FOR CALIFORNIA RESIDENTS ONLY-PROP 65 WARNING:

Some products may contain chemicals such as DEHP, which can cause cancer, birth defects or other reproductive harm. For more info go to www.p65warnings.ca.gov

ECO #: W19-0212